



Vibration Diagnostic Guide



Accelerometer Location

Selecting Test Locations


1. Transmission Path
2. Frequency Response
3. Repeatability





Selecting Orientations

1-2-3 1-2-3
 RAT : VAH
 ART : AVH
 TRA : HVA

- Sensor #1 is in line with captive screw
- Sensor #2 is in line with alignment pin
- Sensor #3 is in the remaining plane



Horizontal shaft and Vertical shaft Orientations



Maintenance Types:


- Reactive – Run to Failure
- Preventive – Calendar based
- Predictive – Condition based
- Proactive – Root Cause Analysis

Keys to a Successful Program:

- Complete & repeatable data
- Get Answers, not just Data
- First rate support & training
- Distribute information to planners and managers

Sensor Location Numbering

Start numbering from driver free end.
 Number bearings with flow of energy.



Sensor Location Numbering

Maintenance Planning

- Extreme Faults** – Shutdown machine for immediate repairs to avoid catastrophic failure
- Serious Faults** – Schedule normal repairs for planned outage or maintenance period
- Moderate Faults** – Increase frequency of collection / Review parts availability
- Slight Faults** – Monitor machine
- Retest following maintenance – Verify maintenance performed correctly

Vibration Severity Considerations



- Harmonics – fault getting worse; looseness
- Side-bands – modulation by another signal
- Elevated noise floor – increase in background
- Multiple symptoms – confirming evidence

Sidebands in machine data

- Roller bearing – 1X sidebands
- Gear wear – 1X sidebands
- Motor Bars – 120 Hz sidebands

Analyze Data

1. Find 1X peak and harmonics
2. Identify forcing frequencies
3. Identify machine faults – Imbalance, Misalignment, Bearings, Looseness
4. Compare data between axis / ranges
5. Compare data to baseline
6. Compare data to other like machines
7. Compare data to previous data



Vibration Diagnostic Guide



VdB to IPS

VdB	ips peak	VdB	ips peak	VdB	ips peak
60	0.006	90	0.18	120	5.6
62	0.007	92	0.22	122	7.0
64	0.009	94	0.28	124	8.8
66	0.011	96	0.35	126	1.1
68	0.014	98	0.44	128	1.4
70	0.018	100	0.56	130	1.8
72	0.022	102	0.70	132	2.2
74	0.028	104	0.88	134	2.8
76	0.035	106	1.1	136	3.5
78	0.044	108	1.4	138	4.4
80	0.056	110	1.8	140	5.6
82	0.070	112	2.2	142	7.0
84	0.088	114	2.8	144	8.8
86	0.11	116	3.5	146	11.1
88	0.14	118	4.4	148	14.0


Log to Linear

dB Change	Linear Level Ratio
0	1
3	1.4
6	2
10	3.1
12	4
18	8
20	10

Analyze data with all of the tools available. Get familiar with both linear and log amplitude scales to optimize analysis. Use both CPM and Order Normalized frequency analysis


Amplitude levels –

Each graph shows the same data



Frequency Analysis – CPM vs. Orders


Each graph shows the same data




Order Normalized data is easier to quickly identify shaft vibration and components associated with shaft

Log data allows viewing small peaks and large peaks on the same graph without rescaling of data. VdB scaling eliminates decimals.

Fine-tune Program




1. Reset speed (Normalize data)




2. Find Forcing Frequencies

There is one average record per MID, regardless of number of machines in the MID.




3. Select good data for Averages


More Averages in Baseline increases diagnostic accuracy





No Averages – Mil Std 167-1



5-24 Averages of healthy machine data



Each MID file contains the 'average + 1 sigma' data for each position, axis and range



6 Healthy sets of data, 1X spectral peak =
 1-104 VdB 4-100 VdB
 2-102 VdB 5-98 VdB
 3-100 VdB 6-96 VdB